

Weatherization Assistance in Palm Bay



Figure 1 – Before. Old front door.



Figure 2 - After. New front door and screen door.



Figure 3 - Before. House without solar screens.



Figure 4 - After. House with solar screens.



Figure 5 - Before. Old, rusted, electric water heater.



Figure 6 - After. New, gas water heater.



Figure 7 - Before. Outdoor air conditioning unit with exposed, worn out pipes.



Figure 8 - After. Outdoor air conditioning unit with weatherized pipes.